

## Test Report

No.: XMHL2006003576OT

Date: Jun. 25, 2023

SHANGHAI EASCO ELECTRICAL CO., LTD.

N-7 No.105 Lane 1159 Kanqiao East Road Pudong New District Shanghai China

The following sample(s) was/were submitted and identified on behalf of the client as:

Sample Description	: HALOGEN WIRE DUCT	
Buyer	: GLOBAL	
Manufacture	: SHANGHAI EASCO ELECTRICAL CO., LTD.	
Supplier	: SHANGHAI EASCO ELECTRICAL CO., LTD.	
Country of Destination	: GLOBAL	
Sample Receiving Date	: Jun. 18, 2023	
Test Performing Date	: Jun. 18, 2023 to Jun. 25, 2023	
Test Performed	: Selected test(s) as requested by applicant	
Test Result(s)	: For further details, please refer to the following page(s)	

Signed for and on behalf of Xiamen Branch, SGS-CSTC Co., Ltd.

Beck Hong Approved Signatory



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.sgsx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-eDocument.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's sole responsibility is to its Cilent and this document does not excore a the apriles to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or faisification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. Attention:To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: CN.Doccheck@gss.com

No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86-592) 5766537 f (86-592) 5766460 www.sgsgroup.com.cn 中国・福達・厦门・火炬(翔安)产业区翔虹路31号 邮编: 361101 t (86-592) 5766537 f (86-592) 5766460 e sgs.china@sgs.com



## **Test Report**

## No.: XMHL2006003576OT

Date: Jun. 25, 2023

Page 2 of 2


Test Conducted: As per client's requirements.

Tested Sample: 1 Piece

Test Results: refer to below table

Test item	Test method	Test requirements	Test result
High and low temperature test	SGS In House Method	<ol> <li>High temperature resistance 90°C for 10 hours</li> <li>Low temperature resistance -40°C for 10 hours</li> <li>Check the sample for any damage or other defects that can affect the function After the test.</li> </ol>	PASS

## Sample photo(s):



The testing report/certificate only refers to the sample(s) tested.

\*\*\*End of Report\*\*\*



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <u>http://www.sgs.com/en/Terms-and-Conditions.aspx</u> and, for electronic format documents, subject to Terms and Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction Issues defined therein. Any holder of this document is activated that information contained hereon reflects the Company's findings at the time of tis intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not excented here accept in full, without prior written approval of the Company. Any unauthorized alteration, forgery or faisification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the is document is stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN-Doccheck@gs.com

No.31 Xianghong Road, Xiang/An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86-592) 5766537 f (86-592) 5766460 www.sgsgroup.com.cn 中国・福建・厦门・火炬(翔安)产业区翔虹路31号 邮编: 361101 t (86-592) 5766537 f (86-592) 5766460 e sgs.china@sgs.com